

## REQUIRED: TWO PEOPLE, PHILLIPS HEAD SCREW DRIVER.

After removing the Chilled Rail from the box, position it under the prep table over-shelf. Make sure the cord can reach the intended power outlet.



Locate the mounting brackets on each end of the rail. Using the Phillips head screw driver, remove 1 bracket from each end of the rail.



Lift the Chilled Rail into position underneath the overshelf. Tilt the rail so that the mounting bracket fits on the lip of the over-shelf.







355 E. Kehoe Blvd. Carol Stream, IL 60188 Phone 630-462-8800 Fax 630-462-1460 www.silverking.com





10/01/2013 © Silver King 2012 Printed in U.S.A.







Hold the rail flush to the over-shelf and reattach the mounting brackets to each end.



Slide the rail all the way to the end of the over-shelf so the Chilled Rail can be plugged in.





## **IMPORTANT:**

After installing the Chilled Rail, let it sit for 2 hours before powering up.

See daily cleaning procedures (PM card) prior to initial use.



355 E. Kehoe Blvd. Carol Stream, IL 60188 Phone 630-462-8800 Fax 630-462-1460 www.silverking.com



10/01/2013 © Silver King 2012 Printed in U.S.A.